

ROTHENBERGER

USB / Serial patch cable



CMS

Industrial Equipment Company

6112 North Mesa Street, Suite 127, El Paso, TX 79912

Ph. 866-566-0222, Fax. 915-228-3777

www.cmstools.us

6.1229



R

Bedienungsanleitung bitte lesen und aufbewahren! Nicht wegwerfen!
Bei Schäden durch Bedienungsfehler erlischt die Garantie! Technische Änderungen vorbehalten!

Please read and retain these directions for use. Do not throw them away! The warranty does not cover damage caused by incorrect use of the equipment! Subject to technical modifications.

Lire attentivement le mode d'emploi et le ranger à un endroit sûr! Ne pas le jeter ! La garantie est annulée lors de dommages dûs à une manipulation erronée ! Sous réserve de modifications techniques

¡Por favor, lea y conserve el manual de instrucciones! ¡No lo tire! ¡En caso de daños por errores de manejo, la garantía queda sin validez! Modificaciones técnicas reservadas,

Per favore leggere e conservare le istruzioni per l'uso! Non gettarle via! In caso di danni dovuti ad errori nell'uso, la garanzia si estingue! Ci si riservano modifiche tecniche



Product characteristics

- The patch cable supports the USB specification Rev. 1.1
- It forms a serial port RS232 (COM3, COM4) at a USB port

System requirements

- IBM PC 486DX4-100 MHz CPU or higher
- An available USB port
- CD-ROM drive for driver installation
- Windows 98, Windows ME, 2000, XP

Driver installation (Win98 & ME)

The following steps are necessary for the installation of the Windows 98/ME driver for the USB Serial patch cable:

1. Turn on the computer and enable the USB port within the BIOS set-up so that the USB can be used. Only necessary if the USB ports are not enabled (i.e. in case of the setting being "disabled").
2. Insert the CD as supplied into the CD-ROM drive.
3. Insert the USB Serial patch cable into a free USB port. Windows detects a new hardware component and opens an appropriate window.
4. Now click on NEXT, with the setting already on DRIVER SEARCH FROM CD-ROM in the CD directory D:\USB To Serial (RS232)\ 98~xp (where "D:" denotes the CD-ROM drive).
5. Windows detects the driver and displays 'USB to Serial Cable'. Click on NEXT.
6. Windows now automatically copies the necessary program files to the hard disk. Once Windows has completed the installation, click on FINISH INSTALL.
7. In order to check that the installation has been successful, it is possible to open the 'Device Manager' under 'Settings/Control Panel/System'. After clicking on 'Ports' (COM, LPT), an additional COM port (COM3) should appear (see illustration).

